

If the Vessel has Water Ballast Tanks, state whether of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report. No. 16938 Port Ant.

+ 100A. 1.
10. 28.
No. 2

batten
fitted

rd (if assi
ip and now

10m?

15 APR 1930

S. S. "CIL".

The Boiler Survey became due 2.30.

The Society's Surveyor at Algiers now forwards a letter from the Owners in which they state that as this vessel was already classed with the Bureau Veritas at the time of its purchase they cannot have it classed with this Society.

IT IS SUBMITTED that in the circumstances the class of this vessel might be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of the class at Owners' request.

Withdraw class.

Insert ...

15.4.30.

tems:—

Copper, or
(stat
When

Boats

Masts, Y

Condition

(State

Sails.....

Equipmen

Anchor,

Cables (

„ le

„ R

Hawser

Standin

l in th
main



© 2020

Lloyd's Register
Foundation