

stanchions have been fitted at aft end of joile deck, in way of
at fore end of boiler casings.

3m, 2, 24.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *M. S. Almascos*

Report

Li

No.

88147

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey


Alterations

When due

Polish

9.3.15

Cargo battens not fitted.



© 2021

Lloyd's Register
Foundation

W1162-0057

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

4 : 15 : 2

Received by me,

30/4/25

Ed Deau

10m, 10, 24, -T
quest e d a not to writ