

REPORT of SURVEY for REPAIRS, &c.

May 8th. 41. When handed in at Local Office. May 9th. 41. Port of Hong Kong

Survey held at Hong Kong Date, First Survey Apr. 28th. Last Survey Apr. 28th. 1941.

on the H.M. Naval Dock Steel Sp. "HONGKONG" TONNAGE 1158 Built at Pt. Glasgow By whom Clyde S.B. & Eng. Co. Ltd. When 1917 12

DER DK 854 Owners The Admiralty Managers - Owners' Address - Port belonging to London

veyed Afloat or in Dry Dock? Dry Name of Dock H.M. Naval Dock Destined Voyage -

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

st Report, No. 8587 Port H.Kg

amage cases where the Surveyor has not made a special damage report he is required to state whether he

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR Condition and Annual Freeboard.

essel placed in dry dock, bottom, rudder, keel, stem and stern frame cleaned, examined and

ound in good condition and repcoated.

examined decks, lids, ventilators, casings and coamings and found satisfactory.

ittings and appliances for the protection of openings, guard rails, freeing ports and means of

ccess to crews quarters examined and found in good order.

losing appliances as per Load Line Certificate checked, freeboard verified and found in order.

pt.C11(a) enclosed herewith.

wo corroded links in one length and one in another length of anchor chain cable renewed, on

ompletion cables retested and found satisfactory.

RY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								
THE CONDITION OF THE								
of Decks	Good	State if Tanks have been examined inside	No	Air and Sounding Pipes	-	Copper, or Y.M. of Wood Vessels	-	
Fastenings	-	State if Tanks now tested	No	Dblng. Plates under Sounding Pipes	-	(State if on felt.)	-	
Plating	Good	Bulkheads	-	Engine Room Skylights	Good	When put on, Month	-	Year
in way of sidelights	-	Ceiling	-	Coal Bunkers, Open'gs, Lids, &c.	-	Boats	-	Good
oks	-	Cement or Asphalt (State which.)	-	Oil Bunkers	-	Masts, Yards, &c.	-	
Frames	-	Rudder	Good	Scuppers	Good	Condition, how ascertained	From deck	
Cardinals	-	Steering gear and its connections	-	Cargo Hatchways	-	(State if wedges removed)	No	
aces	-	Windlass	-	Hatches lids	-	Sails	-	
s	-	Have pumps now been examined and found effi-	-	Planking of Wood Vessels	-	Equipment letter	n	
rs	-	cient?	No	Caulking	-	Anchors, No. of	3B 19 1K	
rs	-	Have Sluice Valves now been examined and found	-	Treenails	-	Chain Locker	No	
rs	-	efficient?	No	Breasthooks & Stemson	-	Cables (State if now ranged)	No	
rs	-	Have Watertight Doors now been examined and found	-	Transoms Pointers, & Crutches ditto	-	" length (on board)	Stated correct	
rs	-	efficient?	No	Timbers of Frame at openings ditto	-	" Rule length	210 1,8/16	
rs	-	Have Ventilators and their Coamings been examined	-	Ditto Ditto at other places ditto	-	Hawser & Warps	Good	
rs	-	and found efficient?	Yes	Stringers, Clamps & Shells ditto	-	Standing and Running Rigging	-	
rs	-			Salting (State if examined.)	-			

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

his vessel, as far as seen, is in good and efficient condition and eligible, in my opinion, to

remain as classed and to have record of survey 4-41.

Fee (per Section 29) \$140.00. Annual Freeboard \$ 61.00. Damage or Repair Fee (if any) \$ 15.00. Surveyor's Fee (if any) \$

mittee's Minute FRI. 25 JUL 1941

Character

ned

100

Car. pet. in bulk

Int. for al. free

Bo 5-41

Received by me, 19

Surveyor to Lloyd's Register of Shipping

© 2021 Lloyd's Register Foundation