

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

APR 16 1937

Date of writing Report 10 When handed in at Local Office 15-4-1937 Port of Antwerp
 No. in Reg. Book. 84476 Survey held at Antwerp Date, First Survey 5-4-37 Last Survey 9-4-1937
 on the Machinery of the Wood, Iron or Steel S.S. "Dover Hill" (No. of Visits 3)
 Gross 5815 Vessel built at Newcastle By whom H. H. & Co. Ltd When 1918-3
 Net 3621 Engines made at Newcastle By whom H. E. Marine Eng. Co. When
 569 Boilers, when made (Main) 1918 (Donkey)
 3 Owners Dover Hill S.S. Co. Ltd Owners' Address
 Managers British Ship Management Co. Ltd Port Glasgow Voyage
 1800 If Surveyed Afloat or in Dry Dock afloat in Canal
 Boilers (State name of Dock.)

Port No. 2516 Port R.A.

Parts of Examination and Repairs (if any) B.S.

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on the cause of which must be stated should be separated from repairs due to other causes; and detailed in the body of the report, should be briefly summarised at the end of the report. State also the results of any tests respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he has services for this purpose, and why they were declined.

Report made by anyone else? If so, by whom?

Personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey

None, state for what reasons?

Of the Boilers could not be thus thoroughly examined?

Means, in the absence of internal examination, were adopted by the Surveyor to ensure himself of the thorough efficiency of those parts of each Boiler?

Of internal examination of each boiler 5/4/37 C. & H. Boilers 8/4/37 Port Boilers

Present condition of funnel? good

Examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? 180 lbs per sq. in.

Examine the Safety Valves of Donkey Boiler? Yes

To what pressure were they afterwards adjusted under steam? 180 lbs per sq. in.

Examine all the manholes, doors and their fastenings of the Main Boilers? Yes

and of the Donkey Boilers?

Examine the drain plugs of the Main Boilers?

and of the Donkey Boiler?

Examine all the mountings of the Main Boilers? Yes

and of the Donkey Boiler?

Has now been drawn and examined? no Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has been changed? If so, state reasons

Has now been fitted previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

Is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Done: Examined the three main boilers int and ext. with valves, doors & mountings. Examined the three main boilers under steam and adjusted their safety valves to 180 lbs pressure per sq. in. found all in order.

Observations, Opinion, and Recommendation:— The machinery of this vessel is in a safe working condition, and eligible in our opinion to be continued as classed in the Society's Register Book with full record of B.S. 4-37.

Survey Fee (per Section 29) B.S. £10.50.

Special Damage or Repair Fee (if any) (per Section 29.) £

Travelling expenses (if chargeable) £

Committee's Minute FRI 23 APR 1937

Assigned to B.S. 4-37

Fees applied for 15-4-1937

Received by me, 19

J. L. Dalrymple & J. H. Dalrymple

Engineer Surveyors to Lloyd's Register of Shipping.

Lloyd's Register Foundation

BS due 1.37 held.
It is submitted that
this vessel is eligible for
PDB RECORD BS 4.37.

LH
20/4/37.

W. J. Benson.
Loyds
240706 RADMS
5 JAVIER HILL



© 2020

Lloyd's Register
Foundation