

WRECK SECTION

Rpt. 8.

No.

15 MAY 1951

Received at London Office

No. 5411

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 5th May 1951

When handed in at Local Office

No. in Survey held at PORTIMÃO

Port of LISBON

Reg. Book.

Date, First Survey 20-4-51

Last Survey 21-4-51

1951

68839 on the Wood, Iron or Steel "MAYGLEN"

(No. of Visits 2)

TONNAGE :-

Built at Quebec P.Q.

By whom St. Lawrence Metal & Marine Works

YEAR 1946

MONTH 10th

GROSS 342.499

Owners Elton Tradin Company S.A. of Panama

Owners' Address

UNDER DECK 238.440

NET 117.231

Managers Frederic Ersham, Inc.

(If not already recorded in Appendix to Register Book)

Port belonging to Honduran Puerto RATES

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D Bar D Ba

feet; uE & B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 20523 Port Sen

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER

* for Special Survey

Date of last Survey and of

Periodical Surveys

Machinery and Boiler

Surveys

(Including date of N.B., if any)

+LOCAL

LM010-46 50

with freeboard

L16 (M) 2-49

2-49 10.50

DB32-49

SS ROT. 10.50

T34-48 OG. 8 50

Emade 44 fitted 46

For service in the Baltic & Mediter-
ranean European Coasting including
Great Britain & Ireland but North of
Society's Freeboard (if assigned) as 609 N in sum-
mer. painted on Ship and now verified

OIL ENGINES

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Report To Lloyd's

AGENTS

COPY HERewith

Was a damage report made by anyone else? if so, by whom? No

REPAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE

At the request of Messrs. James Rawes & Co. Ltd. (Lloyd's Agents) attended the above vessel at Portimão to ascertain her position following upon a collision with the steamer "Cabo San Sebastian" on the 15th April 1951.

The vessel was located approx. 400 yards from the shore, lying on the starboard side outside the bar of Portimão in 24 ft. of water at low tide the port side of the vessel being visible and out of water, for about 2'-0", revealing a heavy indentation and hole in the shell in way of the forward end of No. 1 hatch. At high tide in approx. 30 ft. of water the vessel is completely submerged.

A diver was engaged to ascertain if the vessel had suffered further damage and in order to determine if the vessel could be salvaged.

(p.t.o.)

SUMMARY OF DAMAGE REPAIRS :-

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

Renewed ...

Removed and Fairled or Repaired

Fairled or Repaired in place ...

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " In way of sidelights

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

Have the Tanks been examined internally?

Have the Tanks been tested?

Bulkheads

Celling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Suction Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stimson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

State if examined

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diamr.

(on board.)

" Rule length size

Chain Locker

Hawsers & Warps

Standing and Running Rigging

Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This report is forwarded for the information of the Committee.

Survey Fee (per Section 29) :-

Fees applied for,

Special Damage or Repair Fee (if any)

Esc. 2200.00

8-5-1951

Travelling Expenses (if chargeable)

Esc. 800.00

Received by me,

Second Surveyor's Fee (if any)

Esc. 100.00

19

Committee's Minute

FRI. 15 JUN 1951

Character Assigned

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

W1178-0005

... must be taken that the coning paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

The diver also reported the vessel to be lying in soft sand having sunk about 1.5 metres into the sand and in fact the sand was found to be level with the hatch coaming side, starboard side, and part of the vessels cargo of potatoes in bags was lying near the ship.

The mean draft of the vessel loaded was ascertained from the Captain to be 11'-8" and ballast drafts 8'-0" aft and 6'-6" for'd.

200 The Captain stated that some of the tween deck cargo in way of No.1 Hatch had been jettisoned and the No.1 upper deck hatch would therefore be opened, and the approx. weight of cargo left in the ship was stated to be about 420 tons.

No efforts have yet been made to salvage the vessel.

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge																

1/1 Patent made name of Patentee.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

Iron Stream Chain }
or Steel Wire }