

27 OCT 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME..... SAN FLORENTINO..... Rpt. Hfx No. 3665

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(The class is subject to 15 fathoms of chain cable being supplied).

The HALIFAX N.S. Surveyors report a shell plate in engine room (p.s) horizontally cracked about 18".

Temporary repairs have been effected by fitting a joggled plate patch and with cement.

The Surveyors recommend permanent repairs at the next dry docking.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended (and as above.)

As Now, Subject etc.



2019

Lloyd's Register
Foundation

W128-0099