

REPORT OF SURVEY FOR REPAIRS, &c.

Date of Writing Survey: August 25th, 41. Survey turned in on: August 25th, 41. Port of Halifax, Nova Scotia.

Survey held at Halifax, Nova Scotia, Date, First Survey Aug. 6th. Last Survey Aug. 8th. 1941
in the single screw steamship "SAN FLORENTINO".

TUNNAGE—	Built at Newcastle.	Myshon Swan Hunter & Wigham Rich.	1919	4
GROSS 12842	Owners Eagle Oil & Shipping Co..	Officers' Address London		
TONNE DR. 12353	Managers ---	Port belonging to London.		
NET 8107				

Surveyed Afloat or in Dry Dock? Afloat. Name of Dock -----

Cold D. B. or D. B. feet; w.e.b. feet; f. feet
total capacity tons. p.t. tons. d.p.t. tons. m.t. tons.

Notations in the existing Report of survey should be underlined.

N.B.—All alterations in the existing records should be underlined.

Last Report No. 21465. Part C.R.K.

Periodical Surveys, when due, should be reported in detail and variation in the status of the vessel and items regarding to complete the voyage should be communicated. State around the date of Survey, if any, who, in detail, the major and extent of damage, losses and expenses repaired. Details on account of damage (the causes of which need not be stated) should be separated from damages due to other causes; and details being detailed in the body of the report, should be summarized in the form shown below. Wherever the replacement of damage or claims is reported, the particulars should be clearly stated in the space provided on the back of this form, with also the name and address of any person respecting this part.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and if whom and why they were declined.

Not required.

Was a damage report made by anyone else? If so, by whom?

MRS. OR EXAMINATION AS PER RULE 704. wear and tear.

NOW DONE:- Examined crack in shell plate in Engineroom, (p.s.), adjacent to second transverse web frame from After end of engine-room. Crack is about 18" long, running horizontally.

REPAIRS:- (Temporary only.):- A joggled plate patch was fitted to shell plate in way of crack, a cement box being arranged in way, subject to permanent repairs being made at next docking.

The above temporary repairs were found satisfactory.

NAME OF DAMAGE REPAIRS	Shell Plates	Frames	St. Frames	Floors and Bracket Plates	Beams	Lower Bottom Plates	D. Plates	Other Plates
Removed								
Removed and Painted or Repaired								
Painted or Repaired in place								

LIST OF DEFECTS

Bulkheads	Engineroom Skylights
Decking	Coal Bulkers, Openings, Covers, &c.
General or Asphalt	Oil Paints
Bottom	Scrapers
Painting	Cargo Hatchways
In way of machinery	Hatches
Weldings	Plating
Steel plates	Camming
Brackets	Trunnels
Fasteners	Bearings & Stemsh.
Paints	Paints, Painted & Cratches
Glues	Timbers of Frame at openings
Glues	" " other places
Other	Stringers, Clamps & Shakes
Surgeons	Solding
Other portion Painting	(State if examined)
Brackets have been examined internally	
Brackets painted	

SURVEY CONFIRMED TO THE ABOVE.

Engineroom Skylights	Engines, or Y.M. (State if any)
Coal Bulkers, Openings, Covers, &c.	Water Proof, Paints
Oil Paints	Boats
Scrapers	Masts, Tires, &c.
Cargo Hatchways	Condition, how ascertained
Hatches	1940 to 1941
Plating	Equipment issued
Camming	Anchor, No. of
Trunnels	Cables & Seats of same length
Bearings & Stemsh.	Length " forward " mid length " rearward
Paints, Painted & Cratches	Length " forward " mid length " rearward
Timbers of Frame at openings	Chain Locker
" " other places	Holders & Wings
Stringers, Clamps & Shakes	Standing and Running Rigging
Soldering	Sails

General Observations, Opinion as to Class, Recommendation, &c.

This vessel, so far as seen,

state clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notation of the vessel in the Register Book consistent with this survey, thus, for example, "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Survey, 1940," "to remain as classed and to have record of Survey, 1941, and the notation of 1940, 1941."

is in efficient condition, and eligible, in my opinion, to be retained as classed without fresh record of survey, subject to permanent repairs being made to shell plating in way of crack and cement box fitted at this port, in engine-room, (p.s.), adjacent to second transverse frame from Aft, at next docking.

Survey Fee (per Section 2D)

Fee applied for,

Special Damage or Repair Fee (if any)
(per S.P. 2D)

Aug. 25th, 41.

Traveling Expenses (if chargeable)

Received by me,

Second Surveyor's Fee (if any)

1941

A.W. Ralston
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI. 10 OCT 1941

Character Assigned

As now

Subject

Lloyd's Register Foundation