

Presented to Chief Surveyors 18.5.17

Received from Chief Surveyors

VESSEL'S NAME

Steelss Santa Paula

Report


PluNo. 2557**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

❖ 100 A-1. (Steel) Shelter DK with foreboard  
 2 DKS (Steel) + Shelter DK (Steel) 3<sup>rd</sup> DK (Steel) in  
 No. 1 Hold only. Webframes. Longitudinal framing.  
 Cell DB 346. 1209E DT. 32. 826E. FPT. 716. APT 166  
 FK. 6BH. Can. apex. F on shelter DK 31

28.6.17  


18.5.17.

The Surveyors should be requested to state whether the double bottom in way of the Bunks is watertight & whether it has been tested as required by the Rules.

S/O DR 24/5/17

W1281-0170



© 2020

Lloyd's Register  
Foundation