

Im.11.96.

H.

Received 4/3/42


Answered ~

Extract from letter dated 8.1.42. received from
The Surveyors, NEW YORK.

Original letter with "S"

Vessel's Name S.S. "VICTOLITE"

N.Yk.41508. The Surveyor confirms that the thrust shafts were not examined completely at this time. The thrust block was not opened, the bearing only being opened for examination.



© 2019 Lloyd's Register Foundation

Noted
[Signature]
E.

W134 - 0002

Outside Plating

Good

Steering gear and its connections

Good

Cargo Hatchways

Good

Masts

2.
3. Fr
tool

(if as
and no
1?

ble
A

here

or, or
State
fite