

## REPORT

Date of writing Report *18th June 1939*No. in  
Reg. Book.Survey held at *Ri**83538 on the Wood, Iron on*

TONNAGE—

GROSS *3256*UNDER DEK. *2992*NET *2011*Built at *and*By *u*Owners *Max Paulbaum Steam Ship Co.*Managers *James Giering & Co.*Surveyed Afloat or in Dry Dock? *afloat* Name of Dock *✓*

WB=Cell DBor DBa

feet, *uESB*feet; *f*total capacity tons. *FPT* tons; *APT* tons; *MT* feet

N.B.—All alterations in the existing records should be underlined.

Last Report, No. *1744* Port *Rya*

Periodical surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR *equipment*.

*Steel wire ropes on board were examined and found new ropes being supplied of proper size, lengths and number, viz. 100 fms of 4" and 4 coils, 20 fms each, of 2 1/2" ✓*

## SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	of Wood Vessels
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(on Deck)
Coamings	Bulkheads	Engine Room Skylights	on Month
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Year
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Boats
" " in way of sidelights	Rudder	Scuppers	Masts, Tards, &c.
Breasthooks	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained
Transoms	Windlass	Hatches	(State if masts removed)
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Anchors, No. of
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Chain Locker
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems ditto	Cables (State if masts removed)
Floors		Transoms, Pointers, & Crutches ditto	" length mean diamr.
Keelsons		Timbers of Frame at openings ditto	(on board)
Stringers		Ditto Ditto at other places ditto	" Rule length
Inner Bottom Plating		Stringers, Clamps & Belts ditto	Hawser & Varnish
		Salting (State if examined.)	Standing and Running Rigging

## General Observations, Opinion as to Class, Recommendation, &amp;c. This vessel is eligible

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book, consequent upon this survey, the sample: "to remain as classified and to have record of survey, 1-24."

*and without fresh record of survey, subject to renewal.*

applied for,

19

by me,

19

Surveyor to Lloyd's Register of Shipping.

FRI 19 JUL 1940

*Omit class*  
*re-print*

W1358-0003