

COPY.

Lloyd's Register of Shipping.

for Hamburg



Hamburg Report Nr. 24071

Port

of Düsseldorf

26th January, 1939.

This is to Certify that

M a l t e B e r g

the undersigned Surveyor to this Society did at the request of

Messrs. Gutehoffnungshütte A.G. Oberhausen on the 14th and 18th January, 1939, at their works at Sterkrade inspect 1 spare propeller shaft of S. "Ursula Rickmers". The brass liner has been removed and the shaft inspected. It was observed that 6 holes of $5/8$ " diameter and $1/2$ " to $3/4$ " deep had been bored in the shaft for fixing the old liner with brass screws.

The shaft has been turned over and was found to be sound and has been fitted with a new liner.

Results of tests of the material of the liner:

Tensile str. 31,9 Kg.sqmm.

Elongation 20, -% in 4xdiameter.

Identification marks on the shaft:

LLOYD'S
No. 7089 N.
14. 5. 17.
W.M.

.....
: B T. :
: HNP :
.....

Identification marks on the new liner:


LLOYD'S
M.B. 136 A/1
15.12.38.

M. Berg

SURVEYOR TO LLOYD'S REGISTER

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

10.) 20th.11.37. (MADE IN ENGLAND.)



Lloyd's Register
Foundation

W1359. 0144