

Surveyors

Received from Chief Surveyors

NAME STEEL S. S. "HENRY CLAY" Report Phl. No. 3277

For the CHIEF SHIP SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

When due

The Downrator pump has been dispensed with for the present.

* 100 A.1. (Steel) "Shelter Dk. with freeboard"


1 Dk. (steel) and Shelter dk. (steel) and webframes.

Longitudinal Framing.

Cell DB 362' 1434t. DTA 21' 153t. FPT 235t. APT 163t.

FK. 4 BH to Shelter Dk. 3 BH to Upper Dk.

Cem. A & C.P. P 41', B 134', F 46' on Shelter Dk.




AGS.

23.7.19

It is concluded, the bulkheads are the same as in sister vessel, namely 4 Bulkheads to Shelter Dk, and 3 Bulkheads to Upper Dk, also that the Shelter Deck Transverse Beams are as approved but the Surveyors should be requested to state if this is so.

S. O.

31 7 19



© 2021

Lloyd's Register
Foundation

W11467-0025