

1-2
5-26

S.S. "ACCOMAC"

S. Fo. Rpt. 2778

It is submitted the New York Surveyors should be requested to state whether the screw shaft of this vessel is fitted with a continuous liner and, if not, whether the joints have been burned as required by the Rules.

9/9/18
These particulars are not stated in the report.

© 2021

Lloyd's Register
Foundation

4-9-15

W1505-0084