

3m. 1.5.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S. S. MO LINE "

Report Phl.

No. 3269

For the CHIEF SHIP SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24592.)

Survey Survey

When due

The Anchors have been tested by the American Bureau Surveyors.

100 A.1. (steel)

2 Dks (steel).

CO DB 244' 644t. DTA 12' 43t. FPT 64t. APT 99t.

FK. 6 BH. Cem. C.P. P 37', B 76', F 29'.

© 2021

Lloyd's Register
Foundation

AES

8719

W1532-0138

Spacing
BEAMS, Second Deck, Single Angle, Bulb

7 3-438 438 17 3-438 438

Deck, Material & thickness