

Engine Room ... }
TONNAGE FOR FEES... 3498.97

Proportions—Depths to Length—Upper Deck Beam at }
side to top of keel }

13.93

Residence 34.1 m

ed by Chief Ship Surveyor 17.11.14

Received from Chief Ship Surveyor

EL'S NAME

Stuess-Buresk

Rpt.

Rob

No. 8721

e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

It is submitted the approved sketch of
Midship Section & Profile should be returned &
the Surveyor requested to amend same in ink
in order to agree with the report & the vessel
as built

72 Rpt + 2 plans
to be returned 17/11/14

M
17.11.14



© 2021

Lloyd's Register
Foundation

01535-0079

BEAMS, Poop Deck, Angle, Bulb Angle, Plate,
Tee Bulb, or Channel

6 1/2 3 1/4 6 1/2 3 1/4

Bridge Deck Stringer Plate, br'dth & thickness