

COPY.

Lloyd's Register of Shipping.



Port

Hong Kong

14th. September 1941.

This is to Certify that I have

Surveyed the ~~Boiler and Machinery of the~~ Propeller Shafts,
Damage Repairs and Examination for Manila Customs of the
Twin M.V. "DON ESTEBAN" of Iloilo, 1616 Gross Tons, No. 73283
in the Register Book.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of ~~of L.M.C. 9-41.~~ and Tail
Shafts seen O.G. 9-41.


be made in the Register Book in the case of this vessel.

Chas R Rowcliffe

Engineer Surbepor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

W161-0006