

Lt. Western Knight

Seattle 828

Submitted the survey a should be requested to state whether he is correct in stating the diam of the M. P cylinder is 48" in view of the report in other respects being a duplicate of his report No 791 on the Western Ally the machinery being stated to be a duplicate of that fitted in this vessel

SO. 19/5/19.

J. J.

Insert for cert

29/5/19

1.P. Cyl 46" dia

Diam M.P. cyl 48" see letter 31/7/19

J. J. 15.6.19
11.25/2/19

Soldered, Taped and Painted with P.B.