



GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

These boilers have been constructed under Special Survey and in accordance with plans approved July 18-1917. The workmanship and material are both of good quality. The steam drums and sections have been tested by hydraulic pressure to 400 lbs per sq inch, and found tight and sound. They have now been despatched for fitting aboard. To complete the survey, the boilers to be re-erected on board, and tested by hydraulic pressure. All mountings to be examined and fitted. Safety-valves to be adjusted under steam.

Philadelphia:-

Boilers erected on board, mountings examined and fitted, hydraulic test of 400 lbs applied and safety valves adjusted under steam to 200 lbs.

Certificate (if required) to be sent to  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	1/3 July	When applied for,	.....19.....
Special .. .. £	1/3 July	When received,	.....19.....
Donkey Boiler Fee .. .. £	1/3 July		
Travelling Expenses (if any) £	1/3 July		

Alexander Macquatt  
Engineer Surveyor to Lloyd's Register of Shipping.

J. Bellock

Committee's Minute

Assigned

See Phil Rpt 3428



© 2021

Lloyd's Register  
Foundation

DE  
Y  
DE  
Y  
Co  
W  
Po  
Po  
If  
If  
Are  
Are  
Are  
Total  
A  
B  
C  
D  
If are  
Where  
DESCRIP  
Main cab  
Branch c  
Branch c  
Leads to  
Cargo ligh  
DESCRIP  
All 11  
#00.  
#10.  
Joints in c  
In be  
Are all the  
position  
Are there a  
How are the