

SAN ROBERTO

date of build 1913

loading of this ship on the voyage in question has
been examined, and it is considered that this was not a
primary cause of the failure.

[Handwritten signature]

[Handwritten initials]

[Handwritten initials]

7th January, 1953.

Surveyors carrying out S S should be
instructed to pay special attention to the condition
of this ship in view of her age and the heavy
weather damage.

[Handwritten signature]

© 2021

Lloyd's Register
Foundation

W1629-0005