

250,7,13.

Wrecked  
Top Shelf. 34

N/N SAN ROBERTO  
Lettonia EX N.N. "STORAA"

F.E.

Received by Chief Ship Surveyor 3. 10. 13

Received from Chief Ship Surveyor

VESSEL'S NAME M S Helmsloch

Rpt. Sld No. 25859

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 77. 46 Depth "d" 21. 96

Framing: Table No. 3 page 15 Description Bulb angle

Longitudinal No. 29435

Proportions Length = 11. 71  
Depth =

Beams Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100 A. 1 ("Steel") as recommended

$\pm$  100 A. 1 ("Steel")

1 SH (M)

N.B. Cru Sta 129'u E'B 40' f167 1178t JPT 45t. AP 318t  
J.K. 6 BH. Cm. Lays A.M.P. 231' B221' F36'

Lloyd's Register  
Foundation  
3. 10. 13