

L'S NAME Steel S.S. "DUNDRUM CASTLE" Report Grk. No. 17587

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

of Survey

When due

Efficient Repairs have been effected to damage sustained by Collision.

Further damage was sustained by striking Quay Wall, one shell plate and two frames being set in. The Owners propose making the damage good at the first convenient opportunity. In the Surveyor's opinion the efficiency of the vessel is not affected. But it should be stated in the Special Reasons list that this damage requires to be repaired.

The Downton Pump has been dispensed with for the present, but it is concluded the Owners are agreeable to fit same when requested.

100 A-1. (steel).

2 Dks (steel) 4 3<sup>rd</sup> Dk (steel) in N<sup>o</sup> 1 Hdd.

Cell DB 340' 1051 t. FPT 132 t. APT 220 t.

FK. 7BH. pl. com. Lloyd's AYCP. P 50', B 113', F 39'.

It is concluded the thickness of strake next below sheerstrake, clear of bridge is as approved but the Surveyors should be requested to state if this is so.



© 2021

Lloyd's Register  
Foundation

w164-0217