

THE 2nd S.S. No.2 BECAME DUE 11.42.

17 MAR 1943

Sent to Chief Surveyors.....

Received from Chief Surveyors.....


VESSEL'S NAME "EMPIRE ROWAN" Report Gls. No. 66765

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey..... Condition..... ~~When due~~.....

Subject to permanent repairs to indented shell plates D.4 & 5, E.2 & F.5, 15 & 16 and frames in Nos.1 & 2 bilges (s.s.) to indented sheerstrake below deck stringer plate etc. (s.s. abreast mainmast), at the first convenient opportunity, to frames of bulkhead between Nos.1 & 2 holds and defective rivets in Nos.3 & 4 D.B. tank top (leakage) at the first opportunity, to indented shell plate No.4 in 4th strake below sheer at the Owners' convenience, also to (a bower anchor and 60 fathoms of chain cable being supplied and to a bower anchor being verified etc. or a bower anchor supplied).



© 2019

Lloyd's Register
Foundation

W165-0178