


Revised
Ant CS
Jan
2. 11. 13

Repair.

Nos P. 2. and S. 1' 3 cross head bearings re-metallized,
No 1 S. fitted with new twin head and the roller
bearing ring for the twin renewed. (twin worn & head cracked)
New shaft splines fitted to aft h.o. pump.



© 2021

Lloyd's Register
Foundation