

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME HORN SHELL Report N.Yk No. 41328**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

(1st S.S. No. 2 due 12.39 **PARTLY HELD.**) Further Gen. Examination.

When proposed to be completed **EXAMINED 6-41-12 MONTHS**

Portion of Survey remaining to complete:- Bunkers to examine & test, cofferdams & D.B. tanks to test and spaces under engines to examine.

Subject to plates on sternframe E.W. etc. 12.33, 2.35, 8.36, 3.38 and 8.40 being specially examined at the next dry docking and to permanent repairs to stem and stem plating and shell plating (s.s.f) at the first convenient opportunity.

Leakage in A.P.T. requires to be dealt with on vessel's arrival in U.K.

advised Surveyor.

was
23.9.41

Insert in S.R.L:

"Examined 6.41" (12 mos)

(DOCKING DATE 6.41)

S.S. PART HELD.



© 2020

Lloyd's Register
Foundation

W172-0002