

Shaft, dia. of journals

as fitted

460

Crank pin dia.

as per Rule

Mid. length thickness

240

Shaft, diameter

Requires

Hornshelly

Made by

A.E.G. Turbinen-Fabrik.

Deutsche Werft A.G. No. 146.

Stettin

Report No.

1073

A copy of

It is submitted that this Report be ~~returned~~ ^{Sent} to

the ^{Kan.} Surveyors for their guidance and for completion.

[Signature]

Date

24/8/20

Copy Sent
28/8/31.



Lloyd's Register
Foundation
W172-0016

endent Power Pump Direct Suctions to the Engine Room Pipes, etc. and

the Bilge Suction pipes in Holds and Tunnel Well fitted with strum-boxes.

Are the B

Mr Coote



© 2020

Lloyd's Register
Foundation

see see Stettin Report No. 1013) and have been fitted on board at Hamburg