

"NELLIE"

12 OCT 1942

It is submitted that before this case receives consideration the Hull Surveyors should be requested to furnish the mean diameter of the chain cables on board the vessel, at the same time they should be informed that the vessel's equipment, when last reported, was deficient by 2 bower anchors and 75 fathoms of chain cable. They should therefore forward the usual particulars of origin, size, weight and test of new anchors and chain cables which have been supplied for insertion in the appropriate place on the report.

The forging report on the new forward section of the sternframe should be forwarded for record in this Office.

*69/16*

9.10.42

*Classed  
13/10*



© 2019

Lloyd's Register  
Foundation

u 200-0115