

26 JUN 1941

REPORT of SURVEY for REPAIRS, &c.

of writing Report Mar. 20th. 41. When handed in at Local Office Mar. 20th. 41. Port of Hong Kong
in Hong Kong Date, First Survey Mar. 17th. Last Survey Mar. 19th. 1941.
Book. (No. of Visits 2)

0745 on the Wood, Iron or Steel "BENNEVIS"
TONNAGE:— Built at Stockton By whom Richardson Duck & Co. Ltd. When 1918
GROSS 5356 Owners Ben Line Steamers Ltd. Owners' Address —
DER DK. 4831 Managers (W. Thomson & Co.) (if not already recorded in Appendix to Register Book).
T 3247 Port belonging to Leith

veyed Afloat or in Dry Dock? Dry Name of Dock Kowloon Destined Voyage —

B=CellDBorDBa feet; uE&B feet; f feet
al capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

st Report, No. 16952 Port Mdb

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) could be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars could be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR Condition. (Intermediate Docking)

Vessel placed in dry dock, bottom, rudder, keel, stem and stern frame cleaned, examined and placed in good condition and recoated.

REPAIRS:—Wear & Tear.

About 46 feet of loose Port bilge keel removed but not replaced,
shell angle fractured at throat and could not be renewed on account of coal in bunkers.

No. 3 rudder pintle renewed. (found fractured)

Angle Fractured here

INARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
ENT CONDITION OF THE								
Good								
State if Tanks have been examined inside			No					
State if Tanks now tested			No					
Bulkheads								
Ceiling								
Cement or Asphalt (State which.)								
Rudder			Good					
Steering gear and its connections								
Windlass								
Have pumps now been examined and found efficient?			No					
Have Sluice Valves now been examined and found efficient?			No					
Have Watertight Doors now been examined and found efficient?			No					
Have Ventilators and their Coamings been examined and found efficient?			Yes					
Air and Sounding Pipes								
Dblng. Plates under Sounding Pipes								
Engine Room Skylights								
Good Bunkers, Open'gs, Lids, &c.								
Oil Bunkers								
Scuppers								
Cargo Hatchways								
Hatches								
Planking of Wood Vessels								
Caulking								
Treenails								
Breasthooks & Stemson								
Transoms Pointers, & Crutches								
Timbers of Frame at openings								
Ditto Ditto at other places								
Stringers, Clamps & Sheifs								
Salting (State if examined.)								
Copper, or Y.M. of Wood Vessels (State if on Felt.)								
When put on, Month								
Boats								
Masts, Yards, &c.								
Condition, how ascertained								
(State if wedges removed)								
Sails								
Equipment letter								
Anchors, No. of								
Chain Locker								
Cables (State if now ranged)								
length (on board) mean diam.								
Rule length								
Hawser & Warps								
Standing and Running Rigging								

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

This vessel, as far as seen, is in good and efficient condition and eligible, in my opinion, to remain as classed and to have record of survey 3-41. ✓

Survey Fee (per Section 29) \$140.00.

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) \$ 10.00.

Second Surveyor's Fee (if any) £

Committee's Minute

Character Assigned

Fees applied for,

19/3/1941

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

FRI. 4 JUL 1941

100A1



Lloyd's Register Foundation
W26-0007