

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 16-5-41 When handed in at Local Office 17-5-41 Port of SWANSEA

No. in Reg. Book. Survey held at SWANSEA Date, First Survey 7-5-41 Last Survey 12-5-1941 (No. of Visits 4)

73215 on the Wood, Iron or Steel S.S. DIRPHYS

TONNAGE: GROSS 4240 Built at SUNDERLAND

By whom W. PICKERSGILL & SONS LTD When 1917 MONTH 3

UNDER DK. 4020 Owners V.J. PATERAS

Owners' Address (if not already recorded in Appendix to Register Book).

NET 2661 Managers

Port belonging to CHIOS

Surveyed Afloat or in Dry Dock? AFLOAT Name of Dock

Destined Voyage

WB=Ce/D/BorDBa feet; uE&B feet; f feet }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B. - All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12978 Port Bel

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE AND REPAIRS

Damage stated to have been sustained while afloat at Kings Dock Swansea on May 5th 1941 when the M.V. Francois trier came into contact with stem of S.S. DIRPHYS.

FOUND. Evidence of contact by abrasion on Vessels. Painter

NOW DONE Examined. Rudder and Steering gear and found in good order

Steering gear telemotor controls adjusted and steering gear tried over and found satisfactory

NOW DONE REPAIRS Mounting angles re-riveted on two weather deck hatch beams.

P.T.O

SUMMARY OF DAMAGE REPAIRS :-

Renewed ...
Removed and Faird or Repaired ...
Faird or Repaired in place ...

Shell Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items :-

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	" length size (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Ditto Ditto at other places ditto	Standing and Running Rigging
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting (State if examined.) ditto	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptd24, &c."

To remain as now classed without fresh record of survey subject to buckled Foremast being repaired at first convenient opportunity

Survey Fee (per Section 20) £

Fees applied for, 12-5-1941

Special Damage or Repair Fee (if any) £ 3 3 0

Received by me.

Travelling Expenses (if chargeable) £

19

Second Surveyor's Fee (if any) £

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI, 6 JUN 1941

100% subject to buckled Foremast being repaired at first convenient opportunity

L

© 2021

Lloyd's Register Foundation

B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

If Stockless, state Mechanical Tests

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.