





Report of Survey for Repairs, &c., of Engines and Boilers.

at piston repaired  
subsequently the seal was tightened

20/9  
2/8/93



© 2020

Lloyd's Register  
Foundation