

11.20

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME Stat S. S. ANJER

Rpt. Rot

No. 11998

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey Just Entry

*See letter
15-10-21*

It is Submitted before this Case receives Consideration the Surveyors should be requested to State whether the height of the tops of the Margin plate above the base is as shown on the approved plan in view of the depth given for the Margin plate; whether the overlap of the Centre Girders brackets and intermediate frames in the double bottom is as approved and whether the width of the tank Margin brackets at intermediate framing is as approved and not as stated

Dr. 12-10-21



Handwritten initials and date: 12-10-21

Lloyd's Register Foundation

W281-0125

g ...			
Top Deck, Angle, Bulb Angle, Plate, Tee Bulb or Channel	24 1/2	24 1/2	Angles on auto.
			Tie Plates