

Spare Gear.

- 1 Cast iron propeller ✓
 1 Tail shaft with nut complete ✓
 1 Set of bottom end brasses ✓
 1 Set of crosshead brasses. ✓
 2 Bolts & nuts for bottom ends ✓
 2 Bolts & nuts for crossheads. ✓
 2 Main bearing bolts with nuts. ✓
 1 Set of springs for H.P. piston. ✓
 1 Set of springs for I.P. piston. ✓
 1 Slide valve spindle complete ✓
 1 Eccentric rod complete. ✓
 2 Strapps of pump lever complete. ✓
 1 Feedpump plunger. ✓
 1 Set of airpump valves. ✓
 1 Set of feedpump valves. ✓
 1 Set of bilgepump valves ✓
 1 Airpump rod ✓
 2 Sets of coupling bolts. ✓
 2 Eccentric strapps. ✓
 6 Junck ring bolts ✓
 65 Condensor tubes. ✓
 100 Swivels for same. ✓
 26 Boiler tubes ✓
 4 Stay tubes. ✓
 100 Fire bars. ✓

Zungdorff



© 2021

Lloyd's Register
Foundation

W281-0129