

Rpt. 8.

(Received at London Office)

No.

113461

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON BOX 293

No. in Reg. Book 19417 Survey held at on the Wood, Iron or Steel Date, First Survey Tw. L. ANTONIA Last Survey 19... (No. of Visits...)

TONNAGE: GROSS 13967 UNDER DK. 10636 NET 8254 Built at London By whom John W. When 1921 MONTH 12

Owners (Edward White & Co. L.) Owners' Address (If not already recorded in Appendix to Register Book) Managers (...) Port belonging to (...)

Surveyed Afloat or in Dry Dock? Name of Dock (...) Destined Voyage (...)

Cell D Bord Ba feet; uE & B feet; f feet to capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER: * for Special Survey Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any) +10001 +LMC 12.37 Shell etc. with freshms 12.39 10.39 TS. S 12.36 ss. Bkn. No 3-1.24 A 10.39 20. Liv. No. 1-38 RMC

Noted for oil fuel 6.22 FA above 150°F Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes.
Stringers	Engine Room Skylights
Inner Bottom Plating	Coal Bunkers, Openings, Covers, &c.
Have the Tanks been examined internally?	Oil Bunkers
Have the Tanks been tested?	Scuppers
	Cargo Hatchways
	Hatches
	Planking
	Caulking
	Treenails
	Breasthooks & Stemson
	Transoms, Pointers & Crutches
	Timbers of Frame at openings
	" " at other places
	Stringers, Clamps & Shelves
	Salting (State if examined.)
	Copper, or Y.M. (State if on Felt.)
	When fitted, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed.)
	Equipment letter
	Anchors, No. of
	Cables (State if now ranged)
	" length mean diam. (on board.)
	" Rule length size
	Chain Locker
	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

FRI. 25 JAN 1946

Committee's Minute... Character Assigned Omit all particulars (including R.M.C. class) from report of R.B.



Is Certificate required? If so, to be sent to

W293-0005