

Port CARDIFF.

DAI.
40.

24 MAR 1941

Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME "ANGLESEA ROSE" Rpt. Cff No. 53802

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The CARDIFF Surveyors report the vessel afloat and on account of damage through collision, some shell plating on the starboard side of Nos. 3 and 4 holds found indented and pierced and framing in way and bunker forward bulkhead buckled, the bulwarks etc. set in.

Temporary and partial repairs have been effected.

The Surveyors recommend the indented shell plating and framing starboard side of Nos. 3 and 4 holds and bunker bulkhead (s.s) be permanently repaired at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As Now, Subject, etc.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

© 2020 Lloyd's Register Foundation

W3 - 0078

Equipment letter
Anchors, No. of