

Port of GENOA.

Continuation of Report No. 15186 dated 7/2/38.

on the

plating was found somewhat corroded and this has now been dealt with.

NOW DONE FOR SCREW SHAFT- Screw shaft, continuous liner, withdrawn, examined & found in good condition.

REPAIRS NOW EFFECTED: FOR WEAR & TEAR-

Port Ford Boiler- Port low furnace found somewhat deformed & now faired.

Starb. Ford. Boiler- All furnaces found somewhat deformed and now faired.

The Owners state that owing to scarcity of material the proposed modification to the boilers (See London letters "E" 13.12.37 & "E" 10.1.38) has been suspended in the meantime.

Al held. One furnace
paired. A crank shaft
changed. S. shaft examd.

this vessel is slighter
 THE RECORD.

27
B 138

838

29

24/8/38

189 Aug 1-38
In the field
5-39
Approved

© 2020

Lloyd's Register
Foundation