

NO RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, LOCK-OUTS, COMBINATIONS OR OTHER LABOUR DISTURBANCES NOR FOR LOSS OR DELAY DUE TO HOLIDAYS, BAD WEATHER, FIRE, ACCIDENT OR ANY OTHER CAUSE BEYOND THE COMPANY'S CONTROL. OFFERS FOR DRY DOCKING ARE SUBJECT TO DOCK BEING AT LIBERTY. ALL TRANSPORTING AT OWNERS RISK.

R. & H. GREEN AND SILLEY WEIR LTD.

TELEGRAMS :
REPAIRS, ALDOCK, LONDON

SHIP REPAIRERS & ENGINEERS.

TELEPHONE :
ALBERT DOCK 2121 (10 LINES)

Works :

BLACKWALL YARD : EAST 2404

SURREY DOCKS : BERMONDSEY 3187 & 3188

ROYAL ALBERT DOCK : ALBERT DOCK 2128
(3 LINES)

MILLWALL DOCK : EAST 1625

CENTRAL WORKS ROYAL ALBERT DOCK :
ALBERT DOCK 1506

TILBURY DOCK : TILBURY 53 & 113

CITY OFFICE : 130-132, LEADENHALL STREET, E.C.3

TELEPHONE : AVENUE 5361 (4 LINES) TELEGRAMS : INTERKNIT, STOCK, LONDON



LLOYDS REGISTER OF SHIPPING
RECEIVED
- 3 NOV 1941
Ansd. ||
LONDON

General Offices :

Royal Albert Dock,
LONDON, E.16

31st October 1941.

OUR REF. I/II
YOUR REF.

Lloyds Register of Shipping
Fenchurch Street,
London, E.C.3.

Dear Sirs, s.s. "Inanda"

We herewith enclose duplicate prints of the Electric wiring circuits and Main Switchboard for the above vessel, and shall be pleased if you will confirm that they are in order.

The arrangement is similar to that approved for the S.S. "Inkosi".

Yours faithfully,

R. & H. Green and Silley Weir Ltd.

G. F. Silley
.....General Manager.



© 2020

Lloyd's Register
Foundation

W32-0020

Referred to the Chief Engineer Surveyor

MD

1761 1003



© 2020

Lloyd's Register
Foundation