

If this was not done, state for what reasons? ☒

4m, 11, 38.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "ADAPTITY"

Rpt.

Lon.

No.

109094

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 1


This Survey, due 12.39 <sup>now</sup> ~~partly~~ held ~~now~~  
~~completed~~, and the following repairs carried out (due to wear and tear):-

Some piston covers and pistons renewed and minor repairs effected.

It is submitted the vessel is eligible to remain as classed, with notation of ~~ELMC~~ 8.40, S 8.40 as recommended.

It is concluded the electric ~~light~~ installation has been examined, but this should be confirmed.

lines, pistons, crankshaft, main & bottom end bearings examined  
REPAIRS 8 Piston crowns 2 cylinder covers and 3 scavenge valves renewed. One m



© 2020

Lloyd's Register  
Foundation

W324-0080