

Surveyors

Received from Chief Surveyors

NAME *Steel SS. "ROWAN PARK"* Report *Als* No. *40679*

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.02.)

Free


When due

\* 100 A.1. (steel)

1 Dk. (steel). "Longitudinal framing in Double Bottom, and at decks."

Cell DB a 66', vE 27', f 121', 550 b. FPT 43t. APT 43t.

FK 4 BH. Cem. Wladyd A YCP. P 24', B 65', F 29'

*M*  
  
 17-12-20  
 Lloyd's Register  
 Foundation

W338-0067

ng .....  
 at Deck, Single Angle, Bulb  
 gle, Plate, Tee Bulb, or Channel  
 ng .....

Deck Material thickness  
 Poop Deck Stringer Plate thickness