

CS advanced.
Both screw shafts examined &
propellers repaired after heavy
weather damage.

It is submitted that
this vessel is eligible to
remain as CLASSED. *Both*
S. 12.40.

L.H.
17/3/40.



© 2020

Lloyd's Register
Foundation

TSMY "BENJAMIN FRANKLIN"

Work done for CR.

Examined the following parts:

Port main engine:

No 3 Crank pin & both end bearings

No 1 & 6 Crossheads & top end bearings

Thrust Shaft and bearings.

Starboard Main Engine:

No 1. 3 & 5 Crank pins & both end bearings

No 5. Crosshead & top end bearing.

After main starting air receiver and manholes examined internally.

[Signature]

