

EDGEE ~~Bars~~ amidships $5\frac{1}{2}$ 3 $3\frac{1}{2}$ $5\frac{1}{2}$ 3 $3\frac{1}{2}$ PILLARS in 'tween Deck, size and spacing $2\frac{3}{4}$ " dia

10m, 11, 20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St S. S. "FARFIELD"*Rpt. *And*No. *32903*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

See letter 24.9.21
It is Submitted before this Case receives Consideration the Surveyors be requested to State the dates of the just and last Surveys; Whether the raised Quarter deck Stringer, Stringer angle, plating etc and bridle and forecathle Side plating and riveting are as required and Whether the lower anchors are of an approved pattern

Dr. 22/9/21

M

AD

21.9.21



© 2020

Lloyd's Register
Foundation

Upper Deck, Single Angle, Angle, Plate, Tee, Bulb, or Channel
In way of Long Bridge *2 BEAMS*

Spacing

4	3	28	4	2½	28
2½			2½		

Fourth and fifth Deck Stringer Plate, breadth & thickness

" " " Angles on ditto, No.

Tie Plates outside Hatchways