

LLOYD'S REGISTER OF SHIPPING.

Port

At MALTA.

14th December, 1940.

RETAIN

I have surveyed the Boilers ~~XXXXXXXXXXXX~~ of the Steel T/S "CLAN FRASER" 19 Tons gross of Glasgow on 10th December, 1940, for defects to the Furnaces of the Main Boilers. on 10th December, 1940, for defects to the

and I have furnished the Master with a Report to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction. ~~XXXXXXXXXXXXXXXXXXXX~~

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

~~XX~~

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~


Parts ~~xxx~~ examined and work carried out:-

No.4 Boiler: Examined internally and found in good condition with no traces of oil.
The Two lower and Port Upper furnaces distorted to a maximum of 2 inches. Furnaces were reformed and boiler tested to working pressure.

No.5 Boiler: Examined internally and found in good condition with no traces of oil.
The Two lower furnaces distorted to a maximum of 2 inches. Furnaces were reformed and necessary repairs to brickwork carried out. Boiler tested to working pressure.

COMMANDER (E), R.N.,

Engineer Surveyor to Lloyd's Register.



© 2020

Lloyd's Register Foundation

W374-0043