

1

Fee Paid

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Twin.Sc.S.S. "CLAN FRASER" Report Grk. No. 20703**For the CHIEF SHIP SURVEYOR, ~~and CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

FIRST ENTRYWhen dueTonnage Opening Fitted.

100A1 "With Freeboard"

2 Dks. and Shelter Dk.

Cell.DB 393' 1266t, MT 30' 1076', FPT 68t, APT 126t.

FK, Duct keel forward of Machy. space, 7BH (Coll.BH to Shelter Dk., 6BH to 2nd Dk.) pt.com., Lloyd's A & CP.

P 31', B 103', F 69'

O.L.487.6'

JSW *J.H.W.*

2:3:39.

This is ~~generally~~ a sister ship to the "CLAN FORBES".**RETAIN**

© 2020

Lloyd's Register
Foundation

W574-0047