

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Steel S.S. "Davisian"* Report *Gls.* No. *42532.***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee, the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Excerpt from Sub-Committee's Report 24/5/92.)

Nature of Survey

*First Entry.*

When due

This vessel sustained damage through striking a wharf and plates on the starboard side at the level of the light waterline indented.

Vessel placed in drydock and the damaged shell plating faired as necessary.

✱ 100. A. 1 (Steel) "Shelter Dk. with freeboard."

2 Dks (Stl) & Shelter Dk. (Stl.)

Cell DB 340'963t, DT f 24'641t, DTa 26'670t, FPT 123t, APT 30t,  
FK, 65H to Shelter Dk, 13H to Upper Dk, pt. Cew, Lloyd A. 11.  
B 143' on Shelter Dk.



© 2020

*A.S.J.*  
25/3/23.  
Lloyd's Register  
Foundation

W381-0154