

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MAY 24 1940

Date of writing Report 22-5-1940 When handed in at Local Office 22-5-1940 Port of Belfast

No. in Reg. Book. 23472 Survey held at Belfast Date, First Survey and Last Survey 18-5-1940 (No. of Visits 1)
on the Machinery of the Wood, Iron or Steel S.S. "Dromara"

Tonnage { Gross 723
Net 291 Vessel built at Bowes By whom G. S. White & Co. Ltd. When 1921 Month 6
Engines made at Bowes By whom G. S. White & Co. Ltd. When 1921 Month 6
Nominal Horse Power 98 Boilers, when made (Main) 1921 (Donkey)
No. of Main Boilers 2 Owners John Kelly Ltd. Owners' Address as recorded
No. of Donkey Boilers Managers W. Clint (if not already recorded in Appendix to Register Book.)
Steam Pressure in Main Boilers 180 lb. If Surveyed Afloat or in Dry Dock Afloat. Port Belfast Voyage Coasting
in Donkey Boilers Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. 12624 Port Belfast.

Particulars of Examination and Repairs (if any) Completion BS.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1	12, 38	+LMC 12, 38
SS. Gmk No. 7.	12, 33	TS, CL 11, 38
SS. Bel. No. 1.	-38	

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes, Under steam To what pressure were they afterwards adjusted under steam? 180 lbs/sq in²

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now done:- Main boiler safety valves adjusted under steam.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, & L.M.C. 9, 11, or LMC 140 lb., F.D., &c.) as now seen, is in good condition & eligible in my opinion to remain as classed with fresh record of BS 5, 40 as previously recommended.

Survey Fee (per Section 29)..... £ : : Fees applied for
Special Damage or Repair Fee (if any)..... £ : :
(per Section 29.)
Travelling expenses (if chargeable)..... £ : :
Received by me, 19

R. Muntton
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE 28 MAY 1940

Assigned As 5.40

W382-0093



The Surveyors are requested not to write on or below the space for Committee's Minutes.

Is a Certificate required? If so, to be sent to