

Chief Ship Surveyor 18. 3. 18

Received from Chief Ship Surveyor

NAME Sing. S.S. "TRENEGLOS".

Rpt.

Nwc.

No. 70767

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

urvey

It is submitted this report should be returned and the Surveyors requested to state whether the upper deck beams are fitted  $8 \times 3\frac{1}{2} \times .58$ , or  $8\frac{1}{2} \times 3\frac{1}{2} \times .52$  as shown by pencil on the report.

They should also be requested to fill in the particulars of the steel wire.

Ln. 18/3/18

M  
18. 3. 18



© 2020

Lloyd's Register  
Foundation  
W598-0194



No. 70767

NWC.

18. 3. 18

RETAIN

It is submitted this report should be retained in the files of the Chief Surveyor and the Surveyors requested to state whether the upper deck beams are fitted 8 x 5 1/2 x .58 or 8 x 5 1/2 x .52 as shown by pencil on the report. They should also be requested to fill in the particulars of the steel wire.

18. 3. 18

RETAIN



© 2020

Lloyd's Register  
Foundation

Do. of Houses on  
Do. of excess of  
Do. above Crown  
Engine Room  
Gross Tonnage  
Space  
Crown  
Room  
FOR FE  
ine Room  
igation  
r Tonn  
on Beam  
GTH of  
per Rul  
ons of S  
Leng  
E, Angl  
in peaks  
in way o  
"  
of Fran  
length  
of Fran  
ISED I  
in way o  
"  
ING, de  
IS, dept  
at mid  
in way  
thickne  
depth a  
height  
IS, in C  
state  
spac  
E GIR  
Brack  
GIRDEL  
"  
Angle  
N PLA  
Angle  
"  
Brack  
Heigh  
BOTT  
thickne  
" thi  
"  
" Av  
Bulb A  
acing  
Upper  
Plate, T  
acing  
Second  
gle, Bulb  
gles on  
Spacing  
MS, Poop  
Tee  
Angle