

1

16 DEC 1940

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME..... HOMESIDE ..... Report GLS ..... No. 63147For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey..... DAMAGE ..... When due.....

Subject to indented plates n<sup>o</sup> 6 from forward (P.5) in 2<sup>nd</sup> stoke below sheer and F4 (P.5) being dealt with and doubling plate being fitted on shell plate n<sup>o</sup> 1 in 5<sup>th</sup> stoke below sheer, (5.5f) at the first available opportunity.

Wals  
12.12.40



© 2020

Lloyd's Register  
Foundation

W404-0047

W404-0048