

This semi-built crankshaft
fitted to Star Engine
to replace solid shaft which
broke through after web of
after crank. 9.24
Cause of fracture stated to be
overheating during forging
& inadequate subsequent
annealing. — Report made
by Mr L. Hipley.

Lagarto

GLASGOW REPORT N° 144

W411-0174



© 2021

Lloyd's Register
Foundation