

All crank pins & No 2 journals examined
The surfaces of these parts were found satisfactory
The markings previously reported upon do not
appear to have extended

It is recommended all crank pins be
re-examined before end of 3.42

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

Suggested as recommended

H. R.

12.4.41



© 2020

Lloyd's Register
Foundation