

...and double check again. Boiler separately and make a thorough examination at this time?

W439-0320

2 E

Received from Chief Engineer Surveyor

AME

4
Acroa

Rpt.

Have.

No. 90775-

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~
and Alterations.

his Survey, due 7.33 now ~~partly~~ held

ed, and the following repairs carried out (due to):-

Top screw the ft. examined.

The main boilers have now been fitted with
economizers of the Lunsby-tube type.

The HP cylinders have been fitted with new liners.

is submitted the vessel is eligible to remain as classed, with

n of BS. 11. 33

as recommended.

5(cL) 11.33

dia. of H.P. cylinder is $22\frac{3}{4}$

Lloyd's Register
14/12/33