

COPY.

GEORGE BROWN & CO. (MARINE) LTD.

SHIPBUILDERS & REPAIRERS.

GREENOCK, 27th January 1937.

The Surveyors
Lloyd's Register.
GREENOCK.

Dear Sirs,

No. 201.

Owing to an error in punching the plates for the
Fore Hatch on above vessel, the horizontal bulb angle stiffener
is 14" below top of hatch side as shown on Detailed Sketch in
place of 10" as called for by Freeboard Rules.

We will be pleased to learn if you can approve of
this position in this instance.

Two prints of Hatch Plan enclosed.

Yours faithfully,

GEORGE BROWN & CO. (Marine) LTD

Initialled F.A.B.

Director.



© 2020

Lloyd's Register
Foundation

W449-0364