

25 SEP 1939
8A

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

AKELD

Rpt. Nwc. No. 94862

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

The *Newcastle* Surveyors report this vessel examined afloat on account of damage through *collision*

Damage in way of the boat platform aft port side has now been permanently repaired.

Main sheerstrake, side and deck plating, framing etc. found set in or damaged on port side in way of fore-castle

Temporary repairs have been effected to their satisfaction, and the Surveyors recommend *permanent repairs at the first convenient opportunity.*

It is submitted the vessel is eligible to remain as classed without record of survey, subject as recommended.

f.c.d.
25-9-39
as now, subject, etc.

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

vessel in the Register Book continues to remain as classed and to have

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, the Classing Committee is under any circumstances

classified, with